






















NAN-WK-036-GG



























IMPORTANT: DON'T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.

PART




PARTS


			① 20PCS M6x45 6PCS
			② 12PCS M6x20 4PCS
			③ M4X35 8PCS M6x50 3PCS
			④ M4X14 16PCS M6 3PCS
			⑤ M4X18 4PCS 3PCS
			⑥ 2PCS M6X20 4PCS
			⑦ 2SETS 




3




4



5




6



① X12

② X12


7



⑧ X2



⑨ X4

8




- 10 X3
- 11 X3
- 12 X3


9



- 8 X4
- 13 X4



10



11

