






C13-P1 USB-C to C Cable 60W **USER MANUAL**





Fast Charging-Supported Device

A fast-charge-certified charger and a device capable of the same are required for fast charging.



The cable supports both fast charging and data transfer.

SPECIFICATIONS

| Model Name | C13-P1 |
|------------------------|--|
| Length | 6.6ft / 2m + 3.3ft / 1m+ 1.6ft / 0.5m |
| Weight | 2.29oz / 65g+1.16oz / 33g+0.60oz / 17g |
| Quantity | 3 pcs in total |
| Charging Speed | 20V = 3A 60W (max) |
| Fast Charging Protocol | PD3.1, PD3.0, PD2.0, etc. |
| Material | Nylon Braided |





Contact Us

support@iniu.shop



US/CA +1 (606) 220-6170

Hours: Mon-Fri, 9 AM - 6 PM (EST) (activate "International Roaming" service if you are in CA)



iniushop.com

@iniuofficial

iniu_official





HOMCOZY INC. 15335 FAIRFIELD RANCH ROAD SUITE 200 CHINO HILLS, CA 91709 ☑ hello@iniushop.com

Shenzhen Topstar Industry Co., Ltd. Room 502, Building 20, South Fourth District, Zhangkeng Community, Minzhi Street, Longhua District, Shenzhen

FCC: This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

responsible for compliance could void the user's authority to operate the equipment.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment of permits, user and on a radiale radio frequency energy and, if not installed any provide represents, user and on a radiale radio frequency energy and, if not installed communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment of the following measures.

The provided in the provided provi